

P.O. Box 330 Columbia, IL 62236-0330 618/281-7173 314/241-1785



June 18, 1982

Illinois Environmental Protection Agency 113 West Main Street Collinsville, Illinois 62234

Attention Mr. Kenneth G. Mensing

Reference Brighton Landfill Monitoring Wells

Dear Mr. Mensing:

In response to your letter to Mr. Gene Evans regarding deficiencies in monitoring wells on the Brighton Landfill site, we have been retained by Mr. Evans to check the condition of the monitoring wells and to repair those which are damaged.

All three wells which you indicated had been damaged (G101, G104 & G105) had to be completely replaced. The new piezometers were placed not closer than 8' nor more than about 10' away from the original piezometers. The new piezometers in all cases equal or exceed the original in quality of construction. Installation details for each are attached to this letter. In each case, the original piezometer pipe was sealed with a bentonite cement slurry.

Other existing monitoring wells were checked and found to be in working condition at the time of our visit to the site.

If you have any questions or if we may be of service, please don't hesitate to contact our office.

Respectfully submitted,

JOHN MATHES & ASSOCIATES, INC.

Gary M. Mathes, P.E

GMM/1h

cc: Rama Chaturvede'
Jim Reid
Mike Rapps
Gene Evans

PAN -

RECEIVED

JUNS 1 1982

ILL. E.P.A. - D.L.P.C. STATE OF ILLINOIS





